



OPTION 2
MAST FOOT



OPTION 2

MAST FOOT

94°


MAST IS
RAKED BACK

4°
or
1:14

FRONT

BACK

MAST DOES NOT NEED
TO SIT ON BASE



FIXING TOLLES CORRESPOND TO
EXISTING TABILWACIUE